

# Burlington Tunnel Emergency Repairs: A Case History

by: K. Pidgeon - ECI Rail Constructors, Inc.  
M. Boscardin - Boscardin Consulting Engineers, Inc.  
W. Riehl, III – Rail America, Inc.

RETC - 21 June 2011  
San Francisco

# Presentation Organization


- Project Introduction
- Ground Conditions
- Original Tunnel Construction
- 2008 Rehabilitation
- The Emergency Repairs
- Lining Response/Performance
- Summary and Conclusions



# Project Background

- 340 ft Long, Horseshoe-Shaped with Curved Walls
- 4° Horizontal Curve, 60 ft of Overburden
- Inside Dimensions - 17 ft High by 16 ft Wide
- Constructed by Vermont Central RR 1860 - 1861
- Brick Lining Supported on Limestone Block Footings
- Limestone Cobble Floor
- Owned by New England Central Railroad (Rail America)





**Legend**

- Airports
- Mountains and Hills
- Interstates
- US Highways
- VT State Highways
- Rail Lines
- Town Boundaries
- Roads**
- Class 1-3
- Class 4
- Driveways
- Rivers and Lakes
- Streams**
- Intermittent
- Perennial
- Unassigned
- Cities
- VT State Boundary

0 375 750 1125 ft.

Map center: 442200, 221184

VT State Plane Meters (NAD83)



Scale: 1:3,929

DISCLAIMER: This map is for general reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable. VCGI and the State of Vermont make no representations of any kind, including but not limited to the warranties of merchantability or fitness for a particular use, nor are any such warranties to be implied with respect to the data on this map.

URL: [http://maps.vermont.gov/imf/sites/VCGI\\_basemap/jsp/launch.jsp](http://maps.vermont.gov/imf/sites/VCGI_basemap/jsp/launch.jsp)



# 4 Degree Horizontal Curve



# Ground Conditions

- On the Shores of Lake Champlain
- Tunnel Through a 100-ft-High Sand Ridge
- Fine to Medium Sand
- Wind Blown Sand from Glacial Marine Deltaic Deposits
- Running Sand Conditions Below Ground Water
- Some Varved Clay Encountered During Repairs
- Ground Water Level Below Invert



# Loose Fine-Medium Sand



# Original Tunnel Construction

- Construction Started 1 November 1860
- Construction Completed 17 May 1861
- Ground Reported to be “Quick Sand”
- Vertical Wooden Shield with Top Heading and Bench Excavation, Forepoling
- Initial Lining Contiguous 12-in. x 12-in. Timbers, Backpacking with Cordwood, Timber Invert Struts
- Excavated Dimensions 25 ft High by 22 ft Wide




# Original Tunnel Construction, Con't.

- Used 700,000 Board ft of Lumber
- 2-ft-Thick Brick Masonry Final Lining
- Concrete Fill Between Masonry Timber Linings
- Construction 24/7 – 85 Men in Two Shifts
- Average Tunneling Rate 3 ft per day
- Portals
  - Headwalls - 39 ft High Limestone Masonry 6 ft thick at Bottom
  - Wing Walls – 18 ft Thick at Bottom, 4 ft Thick at Top

# Sketch of Initial Lining


- Excavation  
18.7 cy/ft
- Over Excavation  
1.3 cy/ft
- Concrete Packing  
1.35 cy/ft
- Cordwood Packing  
35 cy/ft
- Timber Lining  
838.2 Board ft/ft



# Tunnel Lining Condition at 148 Yrs Old







# 2008 Pre-Rehab Condition

# 2008 Pre-Rehab Condition





# 2008 Pre-Rehab Condition





# 2008 Pre-Rehab Condition



# 2008 Rehabilitation Plan

- Original Intent of 2008 Rehab
  - Mitigate Lining Distress Due to Weathering, Seepage, Freeze-Thaw, Age and Impacts
  - Apply 6-inch Shotcrete Internal Lining, with Weep Holes
  - Lower Tracks to Compensate for Shotcrete
- Pre-2008 Rehab Included:
  - Shotcrete, Bolting, Pointing, Insertion of Masonry


# Emergency Condition

Developed Rapidly After Floor Removal

- Tunnel Sidewalls Moved Inward
- Additional Cracking Observed
- Immediate Response - Stabilize and Assess



# Wall Movement



TOP  
CRACK

LOWER  
CRACK



# Cracking Caused by Rehab Construction



# 15 Sept – Emergency Concrete Bracing





# Emergency Bracing Slab



# Technical Approach to Repairs and Emergency Response

- Immediately Stabilize Wall Movements
- Monitor Further Wall Movements
- Investigate Causes of Movements
- Evaluate Lining Loads, Stresses, Cracking
- Design Permanent Invert Struts
- Complete Emergency and Original Rehab
- Monitor During and Following Construction



# Lining Coring





# Crack and Survey Monitoring






# Shotcrete Work



# Cross Section of Rigid Track System

Capacity = 28.5k/ft






# Invert Slab Replacement



# Completed Base Slab







Rigid Track  
Structure  
Before  
Concrete



# Test Car



# Concreting New Track Structure





# Grouting Cracks





# 2008 Timeline of Events

- 15 Sept - Install Emergency Invert Brace, ECI Engaged
- 15-22 Sept - Assess Tunnel, Core Lining, Install Monitoring
- 20 Sept - Mill up to 18" off Emergency Concrete Brace
- Mid Sept –Mid Oct – Shotcrete Work
- 14-27 Oct – Replace Emergency Brace Slab in Segments
- Late Oct - Install 18-ft-Long Approach Slab at Each Portal
- 27 Oct – 3 Nov - Construct Rigid Track System
- 3 Nov - Run Test Car for Clearance Check
- 6 Nov - Install Concrete for Rigid Track
- 10 Nov - Pass Test Train
- 10-13 Nov - Finalize Alignment and Surfacing, Turn Over to RR
- 14-21 Nov - Install Grout Tubes and Grout Cracks

# Summary and Conclusion

- Emergency Repair & Rehab Work Completed in 2 Months
- Rapid Response to the Emergency Condition Allowed Completion of the Originally Planned Repairs Close to the Original Schedule
- Flexible, Coordinated and Innovative Construction Approaches Contributed to Success
- Construction of the Original Repair Scheme May Have Been Possible with Low Pressure, Low Vibration Equipment, But Long-Term Performance of the Tunnel May Have Been Compromised without a Permanent Invert Strut.



# Nov 2010 Inspection





# Crack Monitor Nov 2010

- Wall Convergence 0 to 1/4 inch Since November 2008
- Typically 1/8 inch Convergence
- Approximately Equal Estimated Shrinkage of Invert Struts
- No New Cracking or Widening of Cracks Observed







**Questions?**



